building type/use/number of floors

landmark number

ATIONSHIP WITH SURROUNDING BUILDINGS Relationship of

setting to building

-2 -1 0 1/2/3 4 5

Importance as contribution to a cluster/streetscape

-2 -1 0 1/2 3 4 5

ARCHITECTURAL DESIGN VALUATION

-2 -1 0 1 2 3 4 5 Facade proportions

Richness/Excellence of detailing/decoration

-2 -1 0 1 2 3 4 5

Unique visual feature of interest

0 1 2 3 4 5

Example of a rare or unusual style or design

0 1 2 3 4 5

Overall architectural quality

-2 -1 (0) 1 2 3 4 5

PROPOSED FOR FURTHER INVESTIGATION

CORNICE, PARAPET, APPENDAGE

Importance of cornice

to building design -2 -1 0 1 2 3 4 5

Cornice contribution

-2 -1 0 1 2 3 4 5 to streetscape

FACADE CONDITION

Physical condition -2 -1 0 1 2 3 4 5

Paint/Material

-2 -1 0 1 2 3 4 5 color

REMODELING

Appropriateness

of improvements -2 -1 0 1 2 3 4 5

Engle 1-15-16 date

Field Notes

Recently renovated inside.

More significant as part

of alley grouping, if you can

ouer look the cute details.

Review Notes

Junior League Listing

Ttext Index Ifile

☐ Northern California Guide

Other Listing

